


## WORKSTATION ACCESSORIES



Sample connection of the Warmbier strip box ③ at the rear of the workstation



### Part Nr.

Part Nr.	Workstation accessories, includes:
① 1402.663.L	1 table mat 610 x 1220 x 2 mm, see page 18
② 1250.682	1 floor mat 1220 x 2500 x 3,5 mm, see page 13
③ 2200.B	1 barrier strip box for 7 wires connection, see page 77
④ 2200.113	1 grounding plug with a 4 mm ring terminal, see page 78
⑤ 2200.121.10	1 earth connecting box with 2 x 10 mm snaps and 1 x 4 mm banana plug socket, see page 78
⑥ 2250.790	2 grounding cords with protective cap, 10 mm snap and a 4 mm ring terminal, see page 77
⑦ 2050.750.3	1 adjustable wrist strap, see page 74
⑧ 2100.752.3.10	1 coil cord 2,4 m, see page 75



### Part Nr.

1250.473	<b>WORKSTATION</b> as Part Nr. 1250.683, except floor mat
② 1250.47002.L	1 floor mat PVC 1500 x 2000 x 2,0 mm, see page 13